

Inspection Photos
Location Name: Razor 25N
Location ID: 444472, Spill ID 479246



Photo 1 Open excavation at flowline spill just north of Razor 25N location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Razor 25N
Location ID: 444472, Spill ID 479246



Photo 2 Material stored on Razor 25N location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources