

Inspection Photos
Location Name: Almont-Dotsero /6 South
Location #: 459147



Photo #1

Dotsero 1 (05-123-48729) Wellsite

Drilling | DG

Conductor pipe installed.



Photo #2

Almont-Dotsero /6 South

4 wells: North to South

Drilling | DG

4: Wellheads installed.

2: Conductor pipe installed.

(Not in photo)