

**Inspection Photos**  
**Location Name:** Almont-Dotsero /6 South  
**Location #:** 459147



**Photo #1**

**Dotsero 2 (05-123-48725) Wellsite**

**Drilling | DG**

*Conductor pipe installed.*



**Photo #2**

**Almont-Dotsero /6 South**

*4 wells: North to South*

**Drilling | DG**

*4: Wellheads installed.*

*2: Conductor pipe installed.*

*(Not in photo)*