

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-67S96W /1NENW

Location ID: 324116



Photo #5640 from entrance to location.



Photo #5641 Storage tank not labeled.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-67S96W /1NENW

Location ID: 324116



Photo #5642 Sight glass indicates the storage tank is full of an unknown fluid.