

Inspection Photos
Location Name: PEOC-NVG -41-23H
Location ID: 316766



Photo 1. Overview of location taken at entrance facing southwest.



Photo 2. Snow cover prevented ability to follow up on stained soil from previous inspection.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: PEOC-NVG -41-23H
Location ID: 316766



Photo 3. Equipment stored on location.



Photo 4. Staining down southern 2 tanks. Snow cover prevented ability to follow up on stained soil from previous inspection.

