

Attachment B





TANK BATTERY DECOMMISSIONING FORM

| | | | | | | | | | | | |
|---|-----------------------|-----------------|-------------|----------------|--------|---------------------|--|------------------------------|-------------------------------|----|--|
| SITE NAME: RICE 22-1,2 Tank Battery | | | | | | | DATE: 11/4/2021 | REM. PROJECT #: 19554 | WEATHER: PARTLY CLOUDY | | |
| SITE DIRECTIONS: 0.1 mile south on CR 55, tank battery immediately to the east | | | | | | | CLIENT: PDC | | | | |
| LEGALS AND LAT/LONG: 40.388077, -104.545228 | | | | | | | TASMAN PERSONNEL: Mike Connolly | | | | |
| SOIL TYPES: Well Graded Sand - SW | | | | | | | SURFACE GRADIENT: North | | | | |
| SOIL SAMPLING | | | | | | | FACILITY INFRASTRUCTURE | | | | |
| Date/Time | Soil Sample ID | PID (ppm) | Visual | Olfactory | Photo? | Grab or Lab Sample? | EQUIPMENT | | Quantity | | |
| | | | | | | | Above Ground Storage Tank (AST) | | 1 | | |
| 11/4/2021 12:15 | PWV01-B @ 4' | 0.3 | No Staining | No Odor | Yes | Lab | Buried or Partially Buried Vessel | | 1 | | |
| 11/4/2021 12:20 | PWV01-N @ 2.5' | 0.2 | No Staining | No Odor | Yes | On-Hold | Separator | | 1 | | |
| 11/4/2021 12:25 | PWV01-W @ 2.5' | 0.2 | No Staining | No Odor | Yes | On-Hold | Emission Control Device (ECD) | | 1 | | |
| 11/4/2021 12:30 | PWV01-S 2.5' | 0.2 | No Staining | No Odor | Yes | On-Hold | Dump Line | | 1 | | |
| 11/4/2021 12:35 | PWV01-E @ 2.5' | 0.5 | No Staining | No Odor | Yes | Lab | Wellhead | | | | |
| 11/4/2021 12:40 | WDL01 @ 2.5' | 0.6 | No Staining | No Odor | Yes | Grab | Flowline | | | | |
| 11/4/2021 12:45 | SEP01-FL @ 3' | 2.4 | No Staining | No Odor | Yes | Lab | Other: Meter House | | 1 | | |
| 11/4/2021 12:50 | SEP01-DL @ 3' | 10.4 | No Staining | Slight HC Odor | Yes | Grab | Soil Loads Removed | | | | |
| 11/4/2021 12:55 | AST01 @ 0-6" | 0.3 | No Staining | No Odor | Yes | Lab | IMPACTED SOIL IDENTIFIED? | | | | |
| 11/4/2021 13:37 | ECD01 @ 0-6" | 0.8 | No Staining | No Odor | Yes | Grab | ESTIMATED VOLUME OF IMPACTS: | | | | |
| 11/4/2021 13:38 | MH01 @ 0-6" | 0.5 | No Staining | No Odor | Yes | Grab | Date | | Number | CY | |
| 11/4/2021 14:00 | SEP01-DL-B @ 4' | 6.8 | No Staining | Slight HC Odor | Yes | Lab | 11/4/2021 | | | 1 | |
| 11/4/2021 14:02 | SEP01-DL-N @ 2.5' | 5.8 | No Staining | Slight HC Odor | Yes | On-Hold | | | | | |
| 11/4/2021 14:04 | SEP01-DL-W @ 2.5' | 7.7 | No Staining | Slight HC Odor | Yes | On-Hold | | | | | |
| 11/4/2021 14:06 | SEP01-DL-S @ 2.5' | 6.2 | No Staining | Slight HC Odor | Yes | On-Hold | | | | | |
| 11/4/2021 14:08 | SEP01-DL-E @ 2.5' | 7.8 | No Staining | Slight HC Odor | Yes | Lab | Total Removed | | 0 | 1 | |
| 11/4/2021 14:01 | BKG01 @ 2.5' | 0.4 | No Staining | No Odor | Yes | On-Hold | Disposal Facility: WM - Ault | | | | |
| 11/4/2021 14:03 | BKG01 @ 3' | 0.2 | No Staining | No Odor | Yes | On-Hold | Groundwater Recovery | | | | |
| 11/4/2021 14:05 | BKG01 @ 4' | 0.4 | No Staining | No Odor | Yes | On-Hold | DATE GW ENCOUNTERED: | | DEPTH: | | |
| | | | | | | | GROUNDWATER IN CONTACT WITH IMPACTED SOIL? | | | | |
| | | | | | | | | | | | |
| | | | | | | | LNAPL OR SHEEN OBSERVED ON GW? | | | | |
| GROUNDWATER SAMPLING | | | | | | | Date | | BBLS | | |
| Date/Time | Groundwater Sample ID | Depth Collected | Turbid? | Sheen? | Odor? | Photo? | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | Total Removed | | 0 | | |
| | | | | | | | Disposal Facility: | | | | |

Photographic Log

| | | | | | | | |
|---|---------|-----------------|--|------------------------------|---------|-----------------|--|
|  | | |  | | | | |
| | | | | | | | |
| Equipment ID: PWV01-B @ 4' | | Equipment Type: | | Equipment ID: PWV01-N @ 2.5' | | Equipment Type: | |
| Material: | Volume: | Contents: | | Material: | Volume: | Contents: | |
| Notes/Conditions: | | | | Notes/Conditions: | | | |


Photographic Log

| | | | | | | | |
|---|----------------|------------------------|--|-------------------------------------|----------------|------------------------|--|
|  | | |  | | | | |
| | | | | | | | |
| Equipment ID: PWV01-W @ 2.5' | | Equipment Type: | | Equipment ID: PWV01-S @ 2.5' | | Equipment Type: | |
| Material: | Volume: | Contents: | | Material: | Volume: | Contents: | |
| Notes/Conditions: | | | | Notes/Conditions: | | | |



Photographic Log

| | | | | | |
|---|----------------|--|--|----------------------------|--|
|  | | |  | | |
| | | | | | |
| Equipment ID: PWV01-E @ 2.5' | | Equipment Type: | | | |
| Material: | Volume: | Contents: | | Equipment ID: AST01 | |
| | | | | Equipment Type: | |
| Notes/Conditions: | | Material: | | Volume: | |
| | | | | Contents: | |
| | | Notes/Conditions: AST & PWV FOOTPRINT | | | |

Photographic Log

| | | | | | | | |
|---|----------------|------------------------|--|----------------------------------|----------------|------------------------|--|
|  | | |  | | | | |
| | | | | | | | |
| Equipment ID: WDL01 @ 2.5' | | Equipment Type: | | Equipment ID: MH01 @ 0-6" | | Equipment Type: | |
| Material: | Volume: | Contents: | | Material: | Volume: | Contents: | |
| Notes/Conditions: | | | | Notes/Conditions: | | | |
| | | | | | | | |

Photographic Log

| | | | | | | | |
|---|---------|-----------------|--|-----------------------------|---------|-----------------|--|
|  | | |  | | | | |
| | | | | | | | |
| Equipment ID: ECD01 @ 0-6" | | Equipment Type: | | Equipment ID: SEP01-FL @ 3' | | Equipment Type: | |
| Material: | Volume: | Contents: | | Material: | Volume: | Contents: | |
| Notes/Conditions: | | | | Notes/Conditions: | | | |

Photographic Log

| | | | | | | | | | |
|---|--|-----------------|--|-----------|--|--|---------|-----------------|--|
|  | | |  | | | | | | |
| | | | | | | Equipment ID: BKG01 | | Equipment Type: | |
| | | | | | | Material: | Volume: | Contents: | |
| | | | | | | Notes/Conditions: BKG01 @ 2.5' BKG01 @ 3' BKG01 @ 4' | | | |
| Equipment ID: SEP01-DL-B @ 4' | | Equipment Type: | | | | | | | |
| Material: | | Volume: | | Contents: | | | | | |
| Notes/Conditions: | | | | | | | | | |

Photographic Log

| | | | | | | | |
|---|----------------|------------------------|--|--|----------------|------------------------|--|
|  | | |  | | | | |
| | | | | | | | |
| Equipment ID: SEP01-DL-N @ 2.5' | | Equipment Type: | | Equipment ID: SEP01-DL-W @ 2.5' | | Equipment Type: | |
| Material: | Volume: | Contents: | | Material: | Volume: | Contents: | |
| Notes/Conditions: | | | | Notes/Conditions: | | | |

Photographic Log

| | | | | | |
|---|----------------|------------------|--|----------------|------------------|
|  | | |  | | |
| | | | | | |
| Equipment ID: SEP01-DL-S @ 2.5' | | | Equipment Type: | | |
| Material: | Volume: | Contents: | Material: | Volume: | Contents: |
| Notes/Conditions: | | | Notes/Conditions: | | |

Photographic Log

| | | | | | | | | | | | |
|---|--|--|--|--|--|------------------------------|---------|-----------------|-------------------|---------|-----------|
|  | | | | | | | | | | | |
| | | | | | | Equipment ID: | | Equipment Type: | | | |
| | | | | | | Material: | Volume: | Contents: | Material: | Volume: | Contents: |
| | | | | | | Notes/Conditions: AST Bottom | | | Notes/Conditions: | | |
| | | | | | | | | | | | |