



00624694

WELL SITE INSPECTION FORM

WELL NAME #1 UENLING 44-11 API NUMBER 05 - 061 - 06543
OPERATOR UPRC PERMIT NUMBER 89 881
LOCATION SE SE 11 17S 42W COUNTY KIOWA
FIELD WILDCAT INSPECTOR SHELTON

AL/PA/DA INSPECTION RESULTS:

PASS ☒ (Y) Y FAIL (N) DATE 5/22/90 FN FD WO

=====

DATE OF INSPECTION BEFORE/DURING DRILLING

CASING SIZE DEPTH SET CMT VOL WOC
CONSISTENT WITH APD CASING PROGRAM? RETURNS
RIG BOP'S CONTACT

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION

PIPE SET? COMPLETION RIG/ACTIVITY

DRILLING PITS: CLOSED OPEN WELLHEAD SYSTEM INSTALLED

TANK ID: YES NO NA WELL SIGN: YES NO

SKIM PIT: gal TANKS: () bbls

EQUIPMENT

BRADENHEAD PRESSURE FLUID: NO YES TYPE

METER RUN: YES NO WELL STATUS: PR TA SI WELL CAT 3-

AL/PA/DA INSPECTION

DATE PLUGGED: 10/27/89 DATE PERMIT EXPIRED:

HOLE PLUGGED: YES ☒ NO PITS BACKFILLED: YES ☒ NO

MATERIAL BURIED: YES NO NA ☒ SITE CLEAN: YES ☒ NO

BOND RELEASE OK: YES ☒ NO FED HOLE MARKER: YES NO ☒

DATE OF SAFETY/STATUS INSPECTION 5/22/90

COMMENTS RESTORATION COMPLETE

