

Caerus Piceance LLC  
RB1  
Location # 334637



Location/ lack of battery signage



location

Caerus Piceance LLC  
RB1  
Location # 334637



Location



location

Caerus Piceance LLC  
RB1  
Location # 334637



**Lack of stabilization/compaction**



**Lack of stabilization/compaction**





Caerus Piceance LLC  
RB1  
Location # 334637



**Lack of stabilization/compaction**



**Lack of stabilization/compaction**



**Caerus Piceance LLC**  
**RB1**  
**Location # 334637**



**Valve missing cap/plug**

