

Inspection Photos
Location Name: Horsetail 30F PAD
Location ID: 435694



Photo 1 – South Wellheads

Photo 2 – North Wellheads

Inspection Photos
Location Name: Horsetail 30F PAD
Location ID: 435694



Photo 3 – Gas Lift Injection Meter Sheds



Photo 4 – Stained Soil at West Meter Shed

Inspection Photos
Location Name: Horsetail 30F PAD
Location ID: 435694



Photo 5 – Stained Soil at West Meter Shed



Photo 6 – Unused Wellhead Part

Inspection Photos
Location Name: Horsetail 30F PAD
Location ID: 435694



Photo 7 – Signs at Entrance