

# Interim Reclamation Inspection

March 25, 2022

Operator: NGL WATER SOLUTIONS DJ LLC- 10373

Location ID: 450612

Inspection Document #: 697503832

Weld County, CO

SWNW Section 35 T7N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



**Photo 1.** Drone aerial imagery taken 3/25/2022 illustrates the C10B location that was built back in April 2020.

Inspection Photos  
Location Name: NGL /C10B  
Location ID: 450612



**Photo 2.** Photo taken from the southern topsoil stockpile, facing North. Photo illustrates the Operator has failed to prevent weed establishment on the stockpile. Kochia, an annual undesirable weed, was observed throughout the entire stockpile.



Inspection Photos  
Location Name: NGL /C10B  
Location ID: 450612



**Photo 3.** Photo taken from the southwestern location, facing North. Photo illustrates the location has established with Kochia but it appears the location is being mowed to control the undesirable weed.

