

Inspection Photos

API: 071-06408

Operator: OGRIS OPERATING LLC

Inspection Date: 4/21/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06408 | Date: 4/21/2022

Inspection Photos



Photo 1. Facing northeast toward the abandoned location. Additional seeding needs to be performed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06408 | Date: 4/21/2022

Inspection Photos



Photo 2. There were old vehicle tracks across the location which is forming slight erosion. Additional seeding needs to be performed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06408 | Date: 4/21/2022