

Inspection Photos  
Operator: Hilcorp  
API: 067-09409  
Date: 5/5/2022



Photo 1. View of the project area from well pad entrance facing center.



Photo 2. View of the southern project area, showing dense Russian thistle debris along the southern fenceline.



Photo 3. View of the northern project area from the northwestern corner facing eastward. Dense Russian thistle observed here.



Photo 4. View of more Russian thistle debris along the well pad fencelines.



Photo 5. View of the reference area comprised of open grass field, with young grasses and rubber rabbitbrush.