

Interim Reclamation and Stormwater Inspection

May 11, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP - #47120

Location ID: 327393

Inspection Document #: 697503935

Weld County, CO

NENE Section 3 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CANNON #37N-3HZ
Location ID: 327393



Photo 1. Google Earth aerial imagery from 10/6/2013. Photo illustrates the total disturbance area during drilling operations.



Inspection Photos
Location Name: CANNON #37N-3HZ
Location ID: 327393




Photo 2. Google Earth aerial imagery from 9/29/202. Photo illustrates the location after interim reclamation has been completed.



Inspection Photos
Location Name: CANNON #37N-3HZ
Location ID: 327393



Photo 3. Photo taken from eastern interim reclamation area, facing East. Photo illustrates desirable perennial vegetation which is better than reference areas that consist of annual grasses and shrubs.



Photo 4. Photo taken from the southwest interim reclamation area, facing West. See comments under Photo 3.

Inspection Photos
Location Name: CANNON #37N-3HZ
Location ID: 327393



Photo 5. Photo taken from western interim reclamation area, facing West. See comments under Photo 3.



Photo 6. Photo taken from the northwest interim reclamation area, facing Northwest. See comments under Photo 3.

Inspection Photos
Location Name: CANNON #37N-3HZ
Location ID: 327393



Photo 7. Photo taken from western interim reclamation area, facing West. See comments under Photo 3. Photo illustrates trash and debris that has been dumped on location.

