

# Inspection Photos Location Name: Ford H 1, Ford H 3 Location ID: 443654



IMG 01  
Well sign



IMG 02  
Site overview 1/2



**Inspection Photos**  
**Location Name: Ford H 1, Ford H 3**  
**Location ID: 443654**



**IMG 03**  
**Site overview 2/2**



**IMG 04**  
**Upslope of waddles filled with sediment**

**Inspection Photos**  
**Location Name: Ford H 1, Ford H 3**  
**Location ID: 443654**



**IMG 05**  
**Stormwater perimeter ditch**



**IMG 06**  
**Rip rap run down**



**Inspection Photos**  
**Location Name: Ford H 1, Ford H 3**  
**Location ID: 443654**



**IMG 07**  
**Pump control**



**IMG 08**  
**Telemetry**

**Inspection Photos**  
**Location Name: Ford H 1, Ford H 3**  
**Location ID: 443654**



**IMG 09**  
**Lube oil has impacted material**



**IMG 10**  
**Prime mover exhaust muffler**



**Inspection Photos**  
**Location Name: Ford H 1, Ford H 3**  
**Location ID: 443654**



**IMG 11**  
**Wellhead**



**IMG 12**  
**Exhaust muffler has impacted material**



**Inspection Photos**  
**Location Name: Ford H 1, Ford H 3**  
**Location ID: 443654**



**IMG 13**

**Produced water tank, with 2 different NFPA signs**



**IMG 14**

**Flow line risers before meter house**



**Inspection Photos**  
**Location Name: Ford H 1, Ford H 3**  
**Location ID: 443654**



**IMG 15**  
**Wellhead**



**IMG 16**  
**Meter House**



**Inspection Photos**  
**Location Name: Ford H 1, Ford H 3**  
**Location ID: 443654**



**IMG 17**

**Flow line risers before meter house**