

Inspection Photos
Location Name: UPRR 42 Pan AM AP 1
Location ID: 318548



Photo 1 WH sign, beginning to fade and will need to be replaced in the near future.

Photo 2 WH

Inspection Photos
Location Name: UPRR 42 Pan AM AP 1
Location ID: 318548



Photo 3 Pump Jack.

Photo 4 Ancillary equip.