

# Inspection Photos

API: 071-08113

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/10/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08113 | Date: 6/10/2022

## Inspection Photos



**Photo 1.** Facing southwest along the main road near the electric gate. The road and culvert has been repaired. Lat/Long:37.08136,-104.62910



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08113 | Date: 6/10/2022

## Inspection Photos



**Photo 2.** The erosion at the culvert outlet has been repaired with rock rip/rap outlet protection. Areas of disturbance were seeded and hydromulched.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08113 | Date: 6/10/2022

## Inspection Photos



**Photo 3.** There is vegetation beginning to establish where areas of disturbance were previously seeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08113 | Date: 6/10/2022

## Inspection Photos



**Photo 4.** Facing southwest toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08113 | Date: 6/10/2022

## Inspection Photos



**Photo 5.** Facing toward the pit.. The pit is shallow; less than 2 ft. deep and needs to be constructed to allow 2 ft. freeboard. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08113 | Date: 6/10/2022