

Inspection Photos and Issue Report

6/22/2022

Operator: CAERUS PICEANCE LLC #10456

Location ID: 479214

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Location ID: 479214



Photo 1: Photo left shows signage at location entrance. Photo right shows tank battery- facility/tanks require signage/labelling.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 479214



Photo 2: Photos taken from the perimeter of the Location. Photos examples showing that topsoil remains in use at the base of the fill slopes/subsoils of the Location as a berm and sediment trap/pond to manage stormwater. BMPs to minimize erosion and degradation at topsoil stockpiles have not been maintained.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 479214



Photo 3: Photos taken from the perimeter of the Location. Photos examples showing that topsoil remains in use at the base of the fill slopes/subsoils of the Location as a berm and sediment trap/pond to manage stormwater. BMPs to minimize erosion and degradation at topsoil stockpiles have not been maintained.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 479214



Photo 4: Photos taken from the perimeter of the Location. Photo left shows BMPs to minimize erosion , degradation and sediment transport at topsoil stockpiles have not been maintained; off-site sediment transport observed (arrows). Photo left dated 6/22/2022, photos right dated 9/3/2021- sediment transport observed in previous inspection occurring in the same spot.