

Inspection Photos

July 8, 2022

Operator: Beeman Oil & Gas Inc- #7125

Location ID: 429116

Location Name: Bulldog /20-12H-892

Inspection Document #: 702800444

Moffat County, CO

SWNW Section 20 T8N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bulldog /20-12H-892
Location ID: 429116



Photo 1. Photo taken from the northeast shows an overview of the northern portion of the Location. Photo also shows dense cover of cheatgrass (List C Noxious) and Russian thistle (undesirable plant species). Note, interim reclamation has not been performed.



Photo 2. Photo taken from the northeast shows an overview of the southern portion of the Location. Refer to additional Photo 1 comments.

Inspection Photos
Location Name: Bulldog /20-12H-892
Location ID: 429116



Photo 3. Photo shows aerial imagery of the Location from Google Earth. Imagery is dated 10/2019. The white line indicates a ground track walked during the 7/8/2022 inspection showing the approximate disturbance/unreclaimed area.



Photo 4. Photo shows the “Location Drawing” from document #401412004 which shows an estimate of production areas and interim reclamation areas included in variance request document #401291893. Variance expired 5/1/2022. Interim reclamation is required.

Inspection Photos
Location Name: Bulldog /20-12H-892
Location ID: 429116



Photo 5. Photo taken from the center of the Location shows an example of bull thistle, a CO List B Noxious Weed on Location.




Photo 6. Photo taken at the sediment pond to the east of the Location shows an example of Scotch thistle, a CO List B Noxious Weed on Location.

Inspection Photos
Location Name: Bulldog /20-12H-892
Location ID: 429116



Photo 7. Photo taken at the south of the Location shows the pad surface covered with Russian thistle, an undesirable plant species.



Photo 8. Photo taken from the west of the Location shows the pad surface covered with cheatgrass, a CO List C Noxious Weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800444

Inspection Photos
Location Name: Bulldog /20-12H-892
Location ID: 429116



Photo 9. Photo taken from the north of the Location shows an example of missing or insufficient wildlife protection BMPs on a secondary containment stock tank.



Photo 10. Photo taken at the northeast of the Location shows rill erosion occurring on the unstabilized and unprotected cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800444