

# Final Reclamation Inspection

Date: 08/03/2022

Operator: Great Western Operating Company LLC  
-10110

Location ID: 320394

Inspection Document #: 696105333

Adams County, CO

NESE Section 11 T1S R66W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: GREAT WESTERN SHAW "E"

UNIT 1

Location ID: 320394



**Photo 1.** Entrance/start of access road taken south of location, facing northeast. Photo illustrates access road has not been reclaimed and weedy vegetation pictured.

Inspection Photos

Location Name: GREAT WESTERN SHAW "E"

UNIT 1

Location ID: 320394



**Photo 2.** Photo taken from southern portion of location, facing northeast. Location has not been reclaimed and revegetated resulting in bare soil. Debris and gravel/road base remain on site.



Inspection Photos

Location Name: GREAT WESTERN SHAW "E"

UNIT 1

Location ID: 320394



**Photo 3.** Location photo taken from western portion, facing northwest. Oil field equipment remains on location.

Inspection Photos

Location Name: GREAT WESTERN SHAW "E"

UNIT 1

Location ID: 320394



**Photo 4.** Photo taken west of location, facing southeast. Location (highlighted in red) has not been reclaimed or revegetated resulting in bare soil.

Inspection Photos

Location Name: GREAT WESTERN SHAW "E"

UNIT 1

Location ID: 320394



**Photo 5.** Photo taken northwest of location, facing southeast. See comments in Photo 4.

Inspection Photos

Location Name: GREAT WESTERN SHAW "E"

UNIT 1

Location ID: 320394



**Photo 6.** Photo taken on northern portion of location, facing southwest. See comments in Photo 4.



Inspection Photos

Location Name: GREAT WESTERN SHAW "E"

UNIT 1

Location ID: 320394



**Photo 7.** Photo taken from northern/center portion of location, facing south. Location has not been reclaimed and road base/gravel still present.

Inspection Photos

Location Name: GREAT WESTERN SHAW "E"

UNIT 1

Location ID: 320394



**Photo 1.** Photo taken from center of location, facing south. Debris left on site.

