

Final Reclamation Inspection

July 20, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 149008

Inspection Document #: 697504080

Weld County, CO

NE Section 32 T3N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PATINA LANDFARM
Location ID: 149008



Photo 1. COGCC GISOnline aerial imagery illustrates the approximate boundary for the Patina Landfarm.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697504080

WELD COUNTY ROAD 41 (DESIGNATED COLLECTOR ROAD - 40' R.O.W. FROM CENTERLINE)

ENDORLEY CRANE WELD 34.5' x 12'

TANK AND EQUIPMENT STORAGE AREA

SOIL CELL #1 110' x 280'

SOIL CELL #2 100' x 200'

CONTAMINATED SOIL STOCK PILE 150' x 150'

CLEAN SOIL STOCK PILE 100' x 150'

PARKING AREA

PRODUCTION FACILITY

SOIL CELL #3 170' x 1100'

SOIL CELL #4 300' x 1050'

ENDORLEY CRANE WELD 34.5' x 12'

50' R.O.W.

Vicinity Map
1" = 4000 Feet

E104 CORNER

Photo 2. Figure illustrates the site plan.

Inspection Photos

Location Name: PATINA LANDFARM

Location ID: 149008



Photo 3. Photo taken from the eastern landfarm, facing East. Photo illustrates what appears to be Russian wildrye growing sparsely throughout the eastern landfarm. Due to the sparse establishment there is weedy vegetation growing in between.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Number: 697504080

Inspection Photos

Location Name: PATINA LANDFARM

Location ID: 149008



Photo 4. Photo taken from the southeastern landfarm, facing South. Photo illustrates sufficient cover of Russian wildrye that is outcompeting the weedy vegetation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697504080

Inspection Photos
Location Name: PATINA LANDFARM
Location ID: 149008



Photo 5. Photo taken from the south central landfarm, facing South. Photo illustrates an area with no desirable vegetative growth.



Photo 6. Photo taken from the south central landfarm, facing West. See comments under Photo 5.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697504080

Inspection Photos
Location Name: PATINA LANDFARM
Location ID: 149008



Photo 7. Photo taken from the western landfarm, facing East. See comments under Photo 5.



Photo 8. Photo taken from the western landfarm, facing South. See comments under Photo 5.

Inspection Photos
Location Name: PATINA LANDFARM
Location ID: 149008



Photo 9. Photo taken from the northwestern landfarm, facing North. Photo illustrates the establishment of a desirable grass, saltgrass.



Photo 10. Photo taken from the northeastern landfarm, facing South. See comments under Photo 5.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697504080