

Inspection Photos and Issue Report

8/25/2022

Operator: LASSO OIL & GAS LLC - 10654

Location #322475

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



Inspection Photos
Operator Name: LASSO OIL & GAS LLC - 10654
Location #322475



Photo 1: Well head- signage missing



Inspection Photos
Operator Name: LASSO OIL & GAS LLC - 10654
Location #322475



Photo 2: Blow-down tank- incorrect operator information. Weeds.



Inspection Photos
Operator Name: LASSO OIL & GAS LLC - 10654
Location #322475



Photo 3: Drag equipment remaining.



Inspection Photos
Operator Name: LASSO OIL & GAS LLC - 10654
Location #322475



Photo 4: Photo taken from the east end of the Location, facing north. Vegetation in photo is predominantly Jointed Goatgrass.

Inspection Photos
Operator Name: LASSO OIL & GAS LLC - 10654
Location #322475



Photo 5: Jointed goatgrass. .

Inspection Photos
Operator Name: LASSO OIL & GAS LLC - 10654
Location #322475



August 25, 2022

Photo 6: Jointed goatgrass along access road.



Inspection Photos
Operator Name: LASSO OIL & GAS LLC - 10654
Location #322475



Photo 1: Photo taken from the access road south of Utah Gas Corp's Federal-Carbonera 1-2; access road is shared between two Operators (Utah Gas, Locin). Photo example showing erosion control and stabilization BMPs are missing or insufficient along entire access road- erosion degradation and sediment transport evident.

Inspection Photos
Operator Name: LASSO OIL & GAS LLC - 10654
Location #322475



August 25, 2022

Photo 12: Continued from photo 1. Hard hat in photo for scale/reference.