

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403119261

Date Received:
07/27/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Labowskie, Steve

steve.labowskie@state.co.us

.General

sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500062

Inspection Date: 05/31/2022

FIR Submit Date: 06/01/2022

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 443658

Location Name: Ford H Number: 1,2 & 3 County: LA PLATA

Qtrqtr: SENW Sec: 10 Twp: 33N Range: 8W Meridian: N

Latitude: 37.121282 Longitude: -107.707946

FACILITY - API Number: 05-067-00 Facility ID: 443655

Facility Name: Ford H Number: 1

Qtrqtr: SENW Sec: 10 Twp: 33N Range: 8W Meridian: N

Latitude: 37.121282 Longitude: -107.707946

CORRECTIVE ACTIONS:

1 CA# 162379

Corrective Action: Install sign to comply with rule 605.h

Date: 06/30/2022

Response: CA COMPLETED

Date of Completion: 07/26/2022

Operator Comment: Tank sign installed.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

CA from previous inspection Doc# 702500062 has been satisfactorily completed.

2 CA# 162380

Corrective Action: Maintain stormwater BMP's per rule 1002.f

Date: 06/16/2022

Response: CA COMPLETED

Date of Completion: 07/01/2022

Operator Comment: Cleaned out and reset wattles and drainage ditch cleaned out.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

CA from previous inspection Doc# 702500062 has been satisfactorily completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: CA Completed. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Gabby Riley

Signed: _____

Title: Permitting Specialist I

Date: 7/27/2022 3:50:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403119261	FIR RESOLUTION SUBMITTED
403119269	Ford H1 & H3;CA Completion Photos

Total Attach: 2 Files