

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403133024

Date Received:

08/11/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Labowskie, Steve

steve.labowskie@state.co.us

.General

sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500083

Inspection Date: 06/15/2022

FIR Submit Date: 06/16/2022

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 333762

Location Name: CUMMINS,LILA GAS UNIT A-N33N8W Number: 4SWNE County: LA PLATA

Qtrqtr: SWNE Sec: 4 Twp: 33N Range: 8W Meridian: N

Latitude: 37.136692 Longitude: -107.720672

FACILITY - API Number: 05-067-00 Facility ID: 268038

Facility Name: LILA CUMMINS A Number: 2

Qtrqtr: SWNE Sec: 4 Twp: 33N Range: 8W Meridian: N

Latitude: 37.136692 Longitude: -107.720672

CORRECTIVE ACTIONS:

1 ☒ CA# 162741

Corrective Action: Install sign to comply with Rule 605.h.

Date: 07/08/2022

Response: CA COMPLETED

Date of Completion: 03/18/2022

Operator Comment: Installed tank capacity on sign.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

CA from previous inspection Doc# 702500083 has been satisfactorily completed.

2 ☒ CA# 162742

Corrective Action: Control weeds to comply with rule 606.

Date: 07/01/2022

Response: CA COMPLETED

Date of Completion: 06/29/2022

Operator
Comment:

Mechanical removal of weeds as site is a no spray site.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

CA from previous inspection Doc# 702500083 has been satisfactorily completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: CA complete for weed removal and tank sign capacity. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: _____

Title: Permitting Specialist I

Date: 8/11/2022 10:58:21 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403133024	FIR RESOLUTION SUBMITTED
403133030	Lila Cummins A2, CA Completion Photo Sign
403133031	Lila Cummins A2, A3, A4 CA Completion Photos Weeds

Total Attach: 3 Files