

Inspection Photos
Location Name: BIRDMAN USX /AB17-16P
Location #: 310219



Photo #1
Kohlhoff - USX AB 17-16 (05-123-26090) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 15 yds.

Photo #2
Kohlhoff - USX AB 17-16 Battery site
Abandoned: ALL Equipment Removed