

# Inspection Photos

API: 061-06287

Operator: CHEMCO INC

Inspection Date: 10/12/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06287  
Date: 10/12/2022

## Inspection Photos



**Photo 1.** Facing east at the beginning of the access road. The cattleguard is filled in with sediment and needs to be cleaned out and maintained. There is a heavy red panel wired to prevent livestock from crossing cattleguard which makes it difficult to access.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06287 Date: 10/12/2022



## Inspection Photos



**Photo 2.** Facing northeast along the access road. There is erosion along the road that needs to be repaired. Vehicles are avoiding this area causing widening of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06287 Date: 10/12/2022

## Inspection Photos



**Photo 3.** Facing toward the tank battery. The area inside the berm needs to be kept free of vegetation. The fence around the tank needs to be repaired to prevent livestock entry. The berm around the tank needs to be rebuilt to contain a spill.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06287 Date: 10/12/2022



## Inspection Photos



**Photo 4.** Facing toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06287 Date: 10/12/2022

## Inspection Photos



**Photo 5.** Facing west at the north side of the location. This is the area of impacted soils at the PA wellsite. A Remediation Project #22282 has been started.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06287 Date: 10/12/2022



## Inspection Photos



**Photo 6.** Facing west at the north side of the location. This is the area of impacted soils. A Remediation Project #22282 has been started.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06287 Date: 10/12/2022



## Inspection Photos



**Photo 7.** This flowline had previously leaked at red arrow.



**Photo8.** The impacted soils need to be cleaned up and the pipe inspected.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources