

Inspection Photogs
Location Name: Tiffany East 3-17
Location ID: 312126



IMG 01
Well sign



IMG 02
Location overview



IMG 03

Unused trough, 2" pipe and fitting



IMG 04

Unused wire fencing



IMG 05
Weeds at produced water tank



IMG 06
Produced water tank



IMG 07

Produced water tank

IMG 08