



LEASE INSPECTION FORM

NEW WELL

Well Name: Champlin 113 Amoco C
Operator: Mc Cormick
Location: SWSE 19-35 59W
Field: Lone Tree

API #: 05-001 -
Permit #:
County: Adams
Inspector: Brilly

Well Status: ☒ PR ☐ SI ☐ TA ☐ AC* *Forward to UIC

Date of Inspection: 12-5-90

CAPABLE OF PRODUCTION GIVEN EXISTING SURFACE EQUIPMENT: ☒ Y ☐ N

CHANGE IN WELL OR EQUIPMENT STATUS SINCE LAST INSPECTION: ☒ Y ☐ N

LEASE #: MULTIPLE WELL LEASE: ☒ Y ☐ N MULTIPLE WELL T-B: ☒ Y ☐ N

API: 05- -	LEGAL:	WELL #:	STATUS:
API: 05- -	LEGAL:	WELL #:	STATUS:
API: 05- -	LEGAL:	WELL #:	STATUS:
API: 05- -	LEGAL:	WELL #:	STATUS:

LEASE SIGN: ☒ Y ☐ N * TANK ID: ☒ Y ☐ N ☐ NA * TANK BERM: ☒ Y ☐ N ☐ NA *

BRADENHEAD PRESSURE: FLUID: ☒ Y ☐ N TYPE:
TUBING PRESSURE: 25 TUBING-CASING PRESSURE:
LIFT SYSTEM: ☒ NA ☐ FLOWING ☐ PUMP JACK ☒ GAS LIFT ☐ DOWNHOLE PUMP ☐ OTHER

PRODUCTION EQUIPMENT: STORAGE TANKS 2 300 BBLs BBLs VERT H-T HORIZ H-T ☒
SEP GMR OTHER

PRODUCTION EQUIPMENT LOCATION: SWNW 30

OBSERVED METHOD OF WATER DISPOSAL: EVAP PIT ☒ INJECTED* ☐ TANKS/TRUCKED ☐ UNKNOWN ☐ NA

WELL CLASS 3- 1 WATER PROD: ESTIMATED ? REPORTED TDS

*INJECTION FACILITY NAME: LOCATION:

COMMENTS:

DISPOSAL PITS: ☒ Y ☐ N PERMITTED: ☐ Y ☐ N * OIL ON PIT FLUID: ☒ Y ☐ N ☐ NA *
COVERED: ☒ Y ☐ N LINED: ☒ Y ☐ N LINER REQUIRED: ☒ Y ☐ N *

DIMENSIONS: 80 x 100

LOCATION: SWNW 30

COMMENTS: Fenceal; Truck may be dumping? D+D Water Serv

SKIM TANK/PIT: ☒ Y ☐ N TYPE: EARTH ☐ CONCRETE ☒ METAL ☐ WOOD ☐

COVERED: ☐ Y ☐ N OIL ON PIT FLUID: ☐ Y ☐ N ☐ NA *

DIMENSIONS: R-vault

LOCATION: SWNW 30

COMMENTS: Saw ^{water} truck leaving site

COMMENTS: 25 psi FL Thg Rust on polish rod
2- belt broke, 2- intact

RECOMMENDED ACTION:

*VIOLATIONS: ☒ Y ☐ N

NOTICE SENT: ☒ Y ☐ N

DATE:

Verbal - Shickman

Strusburg
622-9494
Driver Duwayne Flowers