

Final Reclamation and Stormwater Inspection

Date: 11/16/2022

Operator: CUTLER BROTHERS - 22170

Location ID: 319838

Inspection Document #: 696105618

Adams County, CO

NENE Section 32 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Cutler #1-D
Location ID: 319838



Photo 1. Taken near the former tank battery location, facing northeast. Photo illustrates the tank battery has been removed; various debris (e.g. pipe, fittings, etc) remain on site and need to be removed to comply with Rule 1004.

Inspection Photos
Location Name: Cutler #1-D
Location ID: 319838



Photo 2. Taken west of the location facing southwest. Photo illustrates a pipeline riser that needs to be removed.

Inspection Photos
Location Name: Cutler #1-D
Location ID: 319838



Photo 3. Taken west of the location, facing east. Photo illustrates a pipeline riser that needs to be removed. Green arrow shows former production pit that needs to be closed and approved by a Form 27.

Inspection Photos
Location Name: Cutler #1-D
Location ID: 319838




Photo 4. Google Earth aerial imagery taken circa 09/2020 illustrating the well, tank battery, and pit in relation to the current land use, a paintball facility.