

Final Reclamation Inspection

September 6th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 322670

Inspection Document #: 701900856

NWSW Section 4 T5N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Achziger 1
Location ID: 322670



Photo 1. 2019 aerial imagery of the well pad, tank battery and access road. Note: well pad and tank battery shared a disturbance.

Inspection Photos
Location Name: Achziger 1
Location ID: 322670



Photo 2. Overview photo of the well pad/tank battery taken at ground level from the eastern edge facing west.



Inspection Photos
Location Name: Achziger 1
Location ID: 322670



Photo 3. Cardinal photos taken from the middle of the well pad/tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Achziger 1
Location ID: 322670



Photo 4. Cardinal photos taken from the middle of the well pad/tank battery. Left photo facing south, right photo facing west. Note: well pad/tank battery appear consistent with the adjacent reference area (see photo 5).

Inspection Photos
Location Name: Achziger 1
Location ID: 322670



Photo 5. Well pad/Tank battery reference area.

Inspection Photos
Location Name: Achziger 1
Location ID: 322670



Photo 6. Gravel remains at the well pad/tank battery access point.

