

Final Reclamation Inspection

October 19th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 322783

Inspection Document #: 701900743

NWSW Section 21 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bragg 1
Location ID: 322783



Photo 1. 2020 aerial imagery of the well pad, tank battery and reference area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number:
701900743

Inspection Photos
Location Name: Bragg 1
Location ID: 322783



Photo 2. Overview photo of the well pad. Note: well pad falls on the edge of an active PDC facility pad.

Inspection Photos
Location Name: Bragg 1
Location ID: 322783



Photo 3. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Bragg 1
Location ID: 322783



Photo 4. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad is dominated by Kochia and does not appear consistent with adjacent reference area (see photo 8).

Inspection Photos
Location Name: Bragg 1
Location ID: 322783



Photo 5. Overview photo of the tank battery taken at ground level from the western edge facing east.

Inspection Photos
Location Name: Bragg 1
Location ID: 322783



Photo 6. Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Bragg 1
Location ID: 322783



Photo 7. Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery is dominated by Kochia and does not appear consistent with adjacent reference area (see photo 8).

Inspection Photos
Location Name: Bragg 1
Location ID: 322783



Photo 8. Tank battery/well pad reference area.