



WELL SITE INSPECTION FORM

WELL NAME WINDSONG #4
OPERATOR COVANAUGH & COV
LOCATION SE NW 11 19S 45W
FIELD CAVALRY

API NUMBER 05 - 061 - 06496
PERMIT NUMBER 87-719
COUNTY KIOWA
INSPECTOR SNELTON

AL/PA/DA INSPECTION RESULTS:

PASS(Y) _____ FAIL(N) _____ DATE _____ FN _____ FD _____ WO _____

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____
DRILLING PITS: CLOSED ☒ OPEN _____ WELLHEAD SYSTEM INSTALLED _____
TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____
SKIM PIT: _____ gal TANKS: () _____ bbls
EQUIPMENT NONE

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____
METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA ☒ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____
HOLE PLUGGED: YES _____ NO _____ PITS BACKFILLED: YES _____ NO _____
MATERIAL BURIED: YES _____ NO _____ NA _____ SITE CLEAN: YES _____ NO _____
BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO _____

DATE OF SAFETY STATUS INSPECTION 11/8/88

COMMENTS PITS BACKFILLED - DIRTWORK ROUGH BUT ACCEPTABLE
WELL T-A OPEN 4 1/2 CSG 2 FT ABOVE GROUND LEVEL
NO EQUIPMENT / TUBING & SUCKER RODS ON GROUND
BY WELL

2/8/89 : STATUS SAME

1800 4/13 : STATUS SAME EXCEPT NO TUBING OR SUCKER RODS ON GROUND
SOME DEBRIS

6/15 STATUS SAME 8/29