

Inspection Photos

January 26, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 418772

Location Name: Kaufman pad 6/21A-24-692

Inspection Document #: 702801198

Garfield County, CO

SWNE Section 24 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Kaufman pad 6/21A-24-692
Location ID: 418772



1/26/23
11,-107.615299
299° NW



Photo 1. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801198

Inspection Photos
Location Name: Kaufman pad 6/21A-24-692
Location ID: 418772



Photo 2. Photos show leaky chemical injection units.



Inspection Photos
Location Name: Kaufman pad 6/21A-24-692
Location ID: 418772



Photo 3. Photos show degradation to the pad surface and lack of stabilization BMPs and tracking controls.



Inspection Photos
Location Name: Kaufman pad 6/21A-24-692
Location ID: 418772



Photo 4. Photos show degradation to the pad surface and lack of stabilization BMPs and tracking controls.



Inspection Photos
Location Name: Kaufman pad 6/21A-24-692
Location ID: 418772



Photo 5. Photos show an example of interim area vegetation. Perennial grasses appear established in portions of the location (left) and sparse in other areas (right).

