

Inspection Photos

January 26, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 413453

Location Name: Kaufman (Pad #7)/23A-24-692

Inspection Document #: 702801200

Garfield County, CO

NWSE Section 24 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**


Department of Natural Resources

Inspection Photos
Location Name: Kaufman (Pad #7)/23A-24-692
Location ID: 413453



Photo 1. Photo taken from the east shows an overview of the location.

Inspection Photos
Location Name: Kaufman (Pad #7)/23A-24-692
Location ID: 413453



1/26/23
+39.510637,-107.615125
232° SW

Photo 2. Photos show staining beneath well API # 045-08454 (left) and wildlife protection BMPs missing on a secondary containment stock tank (right).

Inspection Photos
Location Name: Kaufman (Pad #7)/23A-24-692
Location ID: 413453



Photo 3. Photos show degradation to the pad surface and lack of stabilization BMPs and tracking controls.



Inspection Photos
Location Name: Kaufman (Pad #7)/23A-24-692
Location ID: 413453



1/26/23
18,-107.614871
16° N



Photo 4. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801200

Inspection Photos
Location Name: Kaufman (Pad #7)/23A-24-692
Location ID: 413453



Photo 5. Photo shows an example of interim area vegetation. Perennial grasses appear established.