

Inspection Photos

January 26, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335501

Location Name: DOMMER-66S92W/26NWSE

Inspection Document #: 702801204

Garfield County, CO

NWSE Section 26 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DOMMER-66S92W/26NWSE
Location ID: 335501



Photo 1. Photo taken from the south shows an overview of the location.



Inspection Photos
Location Name: DOMMER-66S92W/26NWSE
Location ID: 335501



Photo 2. Photos show a secondary containment stock tank lacks wildlife protection BMPs (left) and debris (right).

Inspection Photos
Location Name: DOMMER-66S92W/26NWSE
Location ID: 335501



Photo 3. Photos show patches of Scotch thistle (List B Noxious) in the eastern (left) and southern (right) interim areas.

Inspection Photos
Location Name: DOMMER-66S92W/26NWSE
Location ID: 335501



Photo 4. Photo shows an example of interim area vegetation. Perennial grasses appear established.



Inspection Photos
Location Name: DOMMER-66S92W/26NWSE
Location ID: 335501



1/26/23
7804,-107.633684
289° W



Photo 5. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801204