

# Calibration Report

Report Date 9/28/22 11:36 AM

Collection Time

9/28/22 11:35 AM

## Section 1 - Meter

Device ID 107107983

Location Lorencito 11-29-34-66

System

Contact # 719-846-7898

Field

Raton Basin

State

Colorado

Producer

Evergreen Natural Resources

Purchaser

Colorado Interstate Gas

## Section 2 - Setup

Current Plate Size 0.5

Pipe Size 2.067

Atmos. Pressure 11.29

Pressure Base 14.73

Tap Type

Flange

Specific Gravity

0.561

SP Tap Location

Up Stream

Temperature Bias

0

Temperature Base

60

Plate Inspected? ☒ Yes ☐ No

Dirty ☒ Yes ☐ No

Nicked? ☐ Yes ☒ No

Edges Sharp? ☒ Yes ☐ No

Plate Mic'd ☐ Yes ☒ No

Warped? ☐ Yes ☒ No

Seal Ring Damaged? ☐ Yes ☒ No

Pitted ☐ Yes ☒ No

Bevel Downstream ☒ Yes ☐ No

## Section 3 - Meter Tube Inspection

Tube Inspected? ☒ Yes ☐ No

Nicked? ☐ Yes ☒ No

Dirty? ☐ Yes ☒ No

Pitted? ☐ Yes ☒ No

## Section 4 - Calibration Data

DIFFERENTIAL				STATIC PRESSURE				TEMPERATURE			
FOUND		LEFT		FOUND		LEFT		FOUND		LEFT	
Test	Meter	Test	Meter	Test	Meter	Test	Meter	Test	Meter	Test	Meter
0.00	0.00	0.00	0.00	11.29	11.30	11.29	11.30				
100.00	99.98	100.00	99.98	111.29	111.29	111.29	111.29				
75.00	75.00	75.00	75.00	61.29	61.33	61.29	61.33				
50.00	49.95	50.00	49.95	13.90	13.92	13.90	13.92				
33.00	32.96	33.00	32.96								
25.00	24.98	25.00	24.98								

DP check with pressure on SP			
FOUND		LEFT	
DP	SP	DP	SP

Cal. Range		
DP	SP	Temp.
0	0	0
100	111	150

Gas Sample Taken ☐ Yes ☒ No

H2S analysis done ☐ Yes ☒ No  
PPM or %

H2O Analysis Done ☐ Yes ☒ No

## REMARKS

Signature / Company

Date

Calibrated by Mark Summers

2/2/2023

Witness