

Reclamation and Stormwater Inspection

Date: 02/06/2023

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 319807

Inspection Document #: 696105720

Adams County, CO

NESW Section 26 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. Facing east near the tank battery. It appears the operator has mowed the undesirable vegetation as identified in the previous inspection.

Inspection Photos
Location Name: Leech 1
Location ID: 319807



Photo 2. Facing south from tank battery. Some remnants of undesirable vegetation were observed during this inspection that the operator will have to manage for in the future. However, it does appear the operator has mowed around the perimeter of the location.

Inspection Photos
Location Name: Leech 1
Location ID: 319807



Photo 3. Facing northwest at the tank battery. Operator has completed the corrective action and removed the unused equipment previous identified.

Inspection Photos
Location Name: Leech 1
Location ID: 319807



Photo 4. Facing north at the tank battery; photo illustrates that the NFPA placards and other labels on the tank are peeling, cracked, and not legible.