

00653291

Well Name	STATE #1-9	API Number	05 - 061 - 6591
Operator	GIBSON	Permit #	91105
Location	SE SE 9 18S 47W	County	KIOWA
Field	NEE NOSHE	Inspector	SNELTON

AL/PA/DA Inspection Results:

Well Status:

Pass (Y) Y Fail (N) _____ Date 11/6/91 ND DG WO PR SI TA

Date of Inspection Before/During Drilling

[illegible]

Consistent with APD casing Program?	YES	NO	Returns
-------------------------------------	-----	----	---------

Rig	BOP'S	Stage Tool Depth	Cmt. Vol.
-----	-------	------------------	-----------

Date of Inspection Before/During/After Completion

<u>Prod. Csg. Set?</u>	<u>Completion Rig/Activity</u>
------------------------	--------------------------------

Drilling Pits: Closed Open Wellhead Installed: Sign: Yes No

Tank ID: Yes No N/A Skim Tank/Pit: Prod. Tanks: () BBLs

Equipment	Meter Run:	Yes	No
-----------	------------	-----	----

Bradenhead Press:	Fluid:	No	Yes	Type	Well Cat.
-------------------	--------	----	-----	------	-----------

AL/PA/DA Inspection

Date Plugged: 3/91

Date Permit Expired:

Hole Plugged: Yes ☒ No

Pits Backfilled: Yes ☒ No ☐

Material Buried: Yes No N/A o

Site Clean: Yes ☒ No ☐

Bond Release OK: Yes ☒ No ☐ Fed ☐

Hole Marker: Yes No ☒

Date of Safety/Status Inspection 11/16/91

Comments: SITE RESTORED / DOZER STILL ON SITE

Violations: Yes No Notice Sent: Yes No Date Sent: