

Inspection Photos

API: 071-06822

Operator: WAPITI OPERATING LLC

Inspection Date: 3/22/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06822 | Date: 3/22/2023

Inspection Photos



Photo 1. Facing northeast toward the access. Areas of the road are rutted and need to be stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06822 | Date: 3/22/2023

Inspection Photos



Photo 2. Facing northeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06822 | Date: 3/22/2023

Inspection Photos




Photo 3. There has been vehicle disturbance to the interim area which needs to be repaired and stabilized (reseeded).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06822 | Date: 3/22/2023