

Inspection Photos

3/21/2023

Operator: CAERUS PICEANCE LLC #10456

Location #335581

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335581



Photo 1: Photos 1-2 taken from the working pad areas of the Location and access road. Photos show that there are areas that appear to have been graded, however vehicle tracking and degradation have persisted; repairing only by grading is not sufficient. BMPs to minimize erosion, degradation, tracking and sediment transport remain missing or insufficient at the Location and access road.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335581



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335581



Photo 3: Photo shows repair work at secondary containment liner is inadequate.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location #335581



Photo 4: Gas observed bubbling from the Chevron 12D-17D. Operator (pumper) on site was notified of the leak, and provided 24 hour notice to stop leak and ensure good mechanical condition.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources