

Inspection Photos

3/21/2023

Operator: CAERUS PICEANCE LLC #10456

Location #335596

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335596



Photo 1: Photos 1-3 taken from Location entrance and access road. Operator appears to have graded road/pad since previous inspection. Photos examples showing BMPs, including vehicle tracking control measures, remain missing or insufficient to minimize erosion, degradation, tracking and sediment transport during wet conditions. Regrading alone is inadequate to address tracking and stabilization issues.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335596



Photo 2: See comments under photo 1. 6 foot measuring stick in photos for reference.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335596



March 21, 2023

Photo 3: See comments under photo 1. 6 foot measuring stick in photos for reference.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335596



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335596



Photo 5: Photo shows unused pipe equipment remains improperly stored within containment BMP, on the Location

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #335596



Photo 6: Photos show liner integrity, and tank labeling corrective actions have not yet been addressed.