

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUBERG RU 532-7 Pad

Location ID: 439173



Photo # 2960 From entrance to location



Photo # 2961 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 252-2 Pad

Location ID: 324178



Photo # 2962 From entrance to location



Photo # 2963 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 252-2 Pad

Location ID: 324178



Mar 23, 2023 at 12:37:01 PM  
CO



Mar 23, 2023 at 12:38:33 PM  
CO

Photo # 2964 From entrance to location

Photo # 2972 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 252-2 Pad

Location ID: 324178



Photo # 2973 Location



Photo # 2974 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 252-2 Pad

Location ID: 324178



Photo # 3006 Location



Photo # 2975 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 252-2 Pad

Location ID: 324178



Photo # 2976 Location



Photo # 2977 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 252-2 Pad

Location ID: 324178



Photo # 2978 Location



Photo # 2979 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 252-2 Pad

Location ID: 324178



Photo # 3001 – Location



Photo # 3002 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 252-2 Pad

Location ID: 324178



**Photo # 2988 Meter calibration info not conspicuously posted**



**Photo # 2989 Meter calibration info not conspicuously posted**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 252-2 Pad

Location ID: 324178



Photo # 2992 E & P waste in secondary containment



Photo # 2993 E & P waste in secondary containment

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 252-2 Pad

Location ID: 324178



Photo # 2994 E & P waste in secondary containment



Photo # 2995 E & P waste in secondary containment

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 252-2 Pad

Location ID: 324178



Photo # 2996 E & P waste in secondary containment



Photo # 2997 E & P waste in secondary containment

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 252-2 Pad

Location ID: 324178



Photo # 2998 E & P waste in secondary containment



Photo # 2999 E & P waste in secondary containment

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 252-2 Pad

Location ID: 324178



Photo # 3000 E & P waste in secondary containment



Photo # 3008 Tank label missing required info

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 252-2 Pad

Location ID: 324178



Photo # 3009 Tank label missing required info



Photo # 3010 Production unit missing bird protection on burner stack