

# Final Reclamation Inspection

April 20, 2023

Operator: HIGHPOINT OPERATING CORPORATION - #10071

Location ID: 305223

Inspection Document #: 697504619

Weld County, CO

NESE Section 28 T5N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DOW LAURA 14-27  
Location ID: 305223



**Photo 1.** COGCC GISOnline aerial imagery from 2015. This inspection covers the well location/tank battery and access roads.



## Inspection Photos

Location Name: DOW LAURA 14-27

Location ID: 305223



**Photo 2.** Photo taken from a portion of the access road, facing North. Photo illustrates the access road consists mostly of weeds with little perennial vegetation that is not reflective of reference areas.



**Photo 3.** Close up photo taken from a portion of the access road. It does not appear all the gravel has been removed.



Inspection Photos

Location Name: DOW LAURA 14-27

Location ID: 305223



**Photo 4.** Photo taken from the well/tank battery location, facing East. Photo illustrates the location consists mostly of weeds with little perennial vegetation that is not reflective of reference areas.



**Photo 5.** Photo taken from the well/tank battery location, facing North. See comments under Photo 4.

Inspection Photos  
Location Name: DOW LAURA 14-27  
Location ID: 305223



**Photo 6.** Reference photo taken from one of adjacent locations.