

Inspection Photos
Location Name: Johnson C29-04 Pad
Location ID: 459556



Photo #1 Cattle Guard packed with mud



Photo #2 Cattle Guard packed with mud

Inspection Photos
Location Name: Johnson C29-04 Pad
Location ID: 459556



Photo #3 Sign



Photo #4 Lease road needs maintained

