

Operator: EXTRACTION OIL & GAS INC
Location Name: LEECH-61S66W 26NESW
Loc ID: 319807
Inspection: 696105720



Exhibit A

CA: NFPA placards and labels at tank battery are peeling, faded, and torn. Refer to attached inspection photos. Install sign to comply with Rule 605.e.

CA Resolution: To comply with Rule 605.e, new placards were installed and new stenciled numbers are displayed on tanks.