

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Furr /F-03 Pad

Location ID: 335021



Photo #349 From entrance to location.



Photo #351 Unused equipment.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Furr /F-03 Pad

Location ID: 335021



**Photo #352 Unused equipment.**



**Photo #353 Insufficient wild life protections.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Furr /F-03 Pad

Location ID: 335021



**Photo #354 Insufficient wild life protections.**

