

Final Reclamation Inspection

June 2nd, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 322959

Inspection Document #: 701900930

NWSE Section 10 T4N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Brown 20-2
Location ID: 322959



Photo 1. 2022 aerial imagery of the well pad and tank battery.

Inspection Photos
Location Name: Brown 20-2
Location ID: 322959



Photo 2. Overview photo of the tank battery taken at ground level from the southern edge facing north. Note: cattle have moved into the disturbance and grazed the area.

Inspection Photos
Location Name: Brown 20-2
Location ID: 322959



Photo 3. Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Brown 20-2
Location ID: 322959



Photo 4. Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery vegetation density does not appear consistent with adjacent reference area (See photo #9) and has a large amount of sediment/gravel covering the disturbance. Sediment is moving in from a recently added drainage ditch to the south side of the alfalfa field located to the west of the disturbance (see photo #5).

Inspection Photos
Location Name: Brown 20-2
Location ID: 322959



Photo 5. Photos of sediment moving into tank battery disturbance from adjacent alfalfa field.

Inspection Photos
Location Name: Brown 20-2
Location ID: 322959



Photo 6. Overview photo of the well pad taken at ground level from the northern edge facing southeast.



Inspection Photos
Location Name: Brown 20-2
Location ID: 322959



Photo 7. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Brown 20-2
Location ID: 322959



Photo 8. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad has higher vegetation cover than the tank battery and appears consistent with reference area (see photo #9) but has residual sediment moving in from the north. Well pad was also grazed recently.

Inspection Photos
Location Name: Brown 20-2
Location ID: 322959



Photo 9. Well pad and tank battery reference area.