

Inspection Photos
Location Name: Crystal 6-65 22-10 10HN
Location ID: 479191



Pic 1 Stormwater control measures failure.



Pic 2 tanks

Inspection Photos
Location Name: Crystal 6-65 22-10 10HN
Location ID: 479191

Aug 11, 2023 at 2:18:07 PM
39.510897,-104.646246
Elbert County
CEMC



Pic 3 VRT, VRU, ECD, generators

Aug 11, 2023 at 2:16:32 PM
39.511150,-104.646108
Elbert County
CEMC



Pic 4 generators, separator, compressor.

Inspection Photos

Location Name: Crystal 6-65 22-10 10HN

Location ID: 479191

Aug 11, 2023 at 2:17:00 PM
39.511464,-104.645443
Elbert County
CEMC



Pic 5 location

Aug 11, 2023 at 2:17:39 PM
39.512252,-104.645469
Elbert County
CEMC



Pic 6 contaminated soil needs to be removed by wellhead.