

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 34-12 Pad
Location # 324259



**Location Overview: Location is within High Priority/Density
Habitat areas & in close proximity to Black Bear Habitat area.
All drainages contribute to the Colorado River.
Section/Township/Range: 12 6S94W**

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 34-12 Pad
Location # 324259



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 34-12 Pad
Location # 324259



**Photo # 7625 Erosion & transport of sediment onto location/
Insufficient BMP's**



**Photo # 7626 Erosion & transport of sediment onto location/
Insufficient BMP's**

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 34-12 Pad
Location # 324259



**Photo # 7627 Erosion & transport of sediment onto location/
Insufficient BMP's**



**Photo # 7630 Erosion & transport of sediment onto location/
Insufficient BMP's**

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 34-12 Pad
Location # 324259



**Photo # 7632 Erosion & transport of sediment onto location/
Insufficient BMP's**



**Photo # 7633 Erosion & transport of sediment onto location/
Insufficient BMP's**

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 34-12 Pad
Location # 324259



**Photo # 7635 Erosion & transport of sediment onto location/
Insufficient BMP's**



Photo # 7647 Culvert needs maintenance

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 34-12 Pad
Location # 324259



Photo # 7648 Culvert needs maintenance



Photo # 7649 Culvert needs maintenance