

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 34-12 Pad

Location # 324259



Photo # 7599 From entrance to location



Photo # 7600 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 34-12 Pad

Location # 324259



Photo # 7602 Location




Photo # 7603 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 34-12 Pad

Location # 324259



Photo # 7604 Location



Photo # 7619 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 34-12 Pad

Location # 324259



Photo # 7620 Location



Photo # 7636 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 34-12 Pad

Location # 324259



Photo # 7614 Unused equipment



Photo # 7618 Unused equipment



Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 34-12 Pad

Location # 324259



Photo # 7622 Debris

