

Interim and Stormwater Inspection

October 9, 2023

Operator: Investment Equip. LLC, #10330

Location ID: 319633

Inspection Document #:709400530

Adams county, CO

SWNE, Section 22, 2S 57W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Badger Creek 22-41
Location ID: 319633



Photo 1. Photo taken of location sign, facing south



Inspection Photos
Location Name: Badger Creek 22-41
Location ID: 319633

Oct 9, 2023 at 12:56:30 PM
Fort Morgan CO 80701
United States



Photo 2. Photo taken of of wellhead, facing east.

Oct 9, 2023 at 12:56:43 PM
Fort Morgan CO 80701
United States



Photo 3. Photo taken facing west of weeds (kochia & russian thistle) in reclaimed hillside area.



Inspection Photos

Location Name: Badger Creek 22-41

Location ID: 319633

Oct 9, 2023 at 12:56:45 PM



Photo 4. Photo taken facing north towards access road, of perennial grasses and weeds (kochia & russian thistle) in reclaimed area and around wellhead working pad.

Oct 9, 2023 at 12:57:14 PM



Photo 5. Photo taken facing north of of perennial grasses and weeds (kochia & russian thistle) in reclaimed area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 709400530

Inspection Photos

Location Name: Badger Creek 22-41

Location ID: 319633

Oct 9, 2023 at 12:58:05 PM



Photo 6. Photo taken facing northwest, of perennial grasses weeds (kochia) in reclaimed area and around wellhead working pad.

Sep 7, 2023 at 3:32:41 PM



Photo 7. Photo taken facing north of undisturbed area for reference vegetation comparison.

Inspection Photos

Location Name: Badger Creek 22-41

Location ID: 319633

Sep 7, 2023 at 2:58:50 PM
Fort Morgan CO 80701
United States



**Photo 8. Photo taken of location sign.
Tank battery ID 319632.**

Sep 7, 2023 at 2:59:04 PM
Fort Morgan CO 80701
United States



**Photo 9. Photo taken of battery, facing south. This
is an off location tank battery.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 709400530

Inspection Photos

Location Name: Badger Creek 22-41

Location ID: 319633

Sep 7, 2023 at 3:16:24 PM



Photo 10. Photo taken facing north, of large gully with exposed un-stabilized flowlines



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 709400530